




Panel 10.2-1A
Portland Harbor RI/FS
Remedial Investigation Report
Total PCBs - Surface Sediment and Abiotic Media





Panel 10.2-1B
Portland Harbor RI/FS
Remedial Investigation Report
Total PCBs - Subsurface Sediment






Panel 10.2-2A
Portland Harbor RI/FS
Remedial Investigation Report
Total PCDD/Fs
Surface Sediment and Abiotic Media







Panel 10.2-2C
Portland Harbor RI/FS
Remedial Investigation Report
Total PCDD/Fs - Biota




Panel 10.2-3A
Portland Harbor RI/FS
Remedial Investigation Report
DDx - Surface Sediment and Abiotic Media





Panel 10.2-3B
Portland Harbor RI/FS
Remedial Investigation Report
DDx - Subsurface Sediment




FEATURE SOURCES:
Transportation, Property, or Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers
Bathymetric Information: David Evans and Associates, Inc.
Riverbank Type: Oregon Department of Fish and Wildlife











Panel 10.2-4B
Portland Harbor RI/FS
Remedial Investigation Report
Total PAHs - Subsurface Sediment







Panel 10.2-5A
Portland Harbor RI/FS
Remedial Investigation Report
Bis(2-ethylhexyl) phthalate
Surface Sediment and Abiotic Media







Panel 10.2-5C
Portland Harbor RI/FS
Remedial Investigation Report
Bis(2-ethylhexyl) phthalate - Biota











Panel 10.2-6C
Portland Harbor RI/FS
Remedial Investigation Report
Total Chlordanes - Biota




Panel 10.2-7A
Portland Harbor RI/FS
Remedial Investigation Report
Aldrin - Surface Sediment and Abiotic Media




FEATURE SOURCES:
Transportation, Property, or Boundaries: Metro RLIS.
Channel & River miles: US Army Corps of Engineers.
Bathymetric Information: David Evans and Associates, Inc.
Riverbank Type: Oregon Department of Fish and Wildlife.







Panel 10.2-7C
Portland Harbor RI/FS
Remedial Investigation Report
Aldrin - Biota





Panel 10.2-8A
Portland Harbor RI/FS
Remedial Investigation Report
Dieldrin - Surface Sediment and Abiotic Media





Panel 10.2-8B
Portland Harbor RI/FS
Remedial Investigation Report
Dieldrin - Subsurface Sediment














Panel 10.2-10A
Portland Harbor RI/FS
Remedial Investigation Report
Copper - Surface Sediment and Abiotic Media




Panel 10.2-10B
Portland Harbor RI/FS
Remedial Investigation Report
Copper - Subsurface Sediment







Panel 10.2-11A
Portland Harbor RI/FS
Remedial Investigation Report
Zinc - Surface Sediment and Abiotic Media




Panel 10.2-11B
Portland Harbor RI/FS
Remedial Investigation Report
Zinc - Subsurface Sediment








Panel 10.2-12A
Portland Harbor RI/FS
Remedial Investigation Report
Chromium - Surface Sediment and Abiotic Media




FEATURE SOURCES:
Transportation, Property, or Boundaries: Metro RLIS.
Channel & River miles: US Army Corps of Engineers.
Bathymetric Information: David Evans and Associates, Inc.
Riverbank Type: Oregon Department of Fish and Wildlife.








Panel 10.2-13A
Portland Harbor RI/FS
Remedial Investigation Report
Tributyltin Ion - Surface Sediment and Abiotic Media





Panel 10.2-13C
Portland Harbor RI/FS
Remedial Investigation Report
Tributyltin Ion - Biota